Oil Field Environmental Incident Summary

Responsible Party: DENBURY ONSHORE, LLC
Well Operator: DENBURY ONSHORE, LLC
Well Name: CEDAR CREEK UNIT 8B 12-12A-63

Field Name: CEDAR CREEK Well File #: 12103

Date Incident:12/23/2014Time Incident:14:00Facility ID Number:County:BOWMANTwp:130Rng:107Sec:12Qtr:

Location Description: On Location

Submitted By: Josh Cuppy Received By:

Contact Person: Josh Cuppy

5320 LEGACY DR

PLANO, TX 75024-3127

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1 MileDistance Nearest Water Well:1 Mile

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	2	Barrels	2	barrels
Brine	3	Barrels	3	Barrels	3	barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 2/17/2016 Clean Up Concluded: 1/15/2015

Risk Evaluation:

None

Areal Extent:

Contained on location

Potential Environmental Impacts:

None

Action Taken or Planned:

Recovered standing fluid. Wash area and unti. Backdrag.

Wastes Disposal Location: Disposal

Agencies Involved:

Updates

Date: 12/24/2014 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a stuffing box leak, remained on location on constructed well site according to the report. NDIC retains oversight.